



CAUTION: PROTECT BALLS AND RACES FROM SAWDUST, DIRT, PAINT, ETC. SHOULD BEARING BECOME "ROUGH" FROM DIRTY RACES, FLUSH THOROUGHLY WITH HOT SOAPY WATER, RINSE, OVEN DRY AND RE-OIL.



PART STAMPED WITH TRIANGLE NAME STAMP

3	BALLS	4	BALL	1
2	2823	PLAIN RACE	1	
1	9486	STAMPING	1	
DET	PART NUMBER	DESCRIPTION	AMT	
B	TRIANGLE MANUFACTURING CO. OSHKOSH, WI.			

NAME 4" LAZY SUSAN BEARING

USED IN 4C SERIES

FIT	////
PLATING	ELECTRO-GALV
MATERIAL	SEE DETAILS
ALL DIMS ±.020 UNLESS SPECIFIED	

DATE	11-25-59	PART NO.	
DRAWN	LML		
CHECKED	MJK		
SCALE	1 / 1		

4C

CHANGE LEVEL
H 09-05-12